CABIN AIR FILTER

Corteco Service Information No. 00020-EN www.corteco.com www.ecatcorteco.com

	Service Information: Corteco No	Bushing with hydro fluid 49371536
	OE-Reference	31126851255; 31126851261; 31126855743
	Make	BMW
20-	Model	1 (F20); 2 (F22); 3 (F30); 4 (F33)
	Engine	View www.ecatcorteco.com for detailed information

## CHASSIS UPDATE HYDRO BUSHING 49371536

Bushing 49371536 includes an integrated adjustable hydraulic damper that responds to different vibration frequencies and amplitudes. This allows the bushing to adjust its dynamic properties depending on road input leading to superior driving comfort.

Counterfeit parts or cheap replicas do not have these characteristics and are not in line with the high OE standards.

Don't take a risk – Choose Corteco original quality.







Specific product design to fulfill OE requirements



High quality raw materials for high-level service parts



Efficient production processes



Global supply chain, dedicated to the aftermarket



